

| <u>Compatibility List</u> | <u>First Page of Section</u> |
|----------------------------------|-------------------------------------|
| Tape Drives | 2 |
| Virtual Tape Libraries | 5 |
| Physical Tape Libraries | 6 |
| ACSLs Supported Devices | 13 |

General Information

Oracle Secure Backup supported tape devices will work with all supported operating systems unless otherwise noted in the comments.

Tape drives and tape libraries are independent; A supported library may utilize any supported tape drive as offered by the tape library manufacturer. Please confirm support for the tape drive and library.

Mixed media within one library is not supported by Oracle Secure Backup.

All devices on this matrix are considered to be supported by Oracle Secure Backup with all firmware versions currently supported by the manufacturer. The latest firmware version tested has been included as a reference. Oracle Secure Backup does not always test with newer firmware releases unless the vendor recommends re-testing based on a change(s) which may affect Oracle Secure Backup, however, newer versions are still supported. If a problem arises, it may be necessary to install the latest firmware tested until the issue resolved.

Oracle Secure Backup does not support tape drives or libraries that are not listed on this compatibility matrix.

SCSI and Fibre channel connectivity is qualified with all supported platforms unless otherwise noted on Oracle Certify on Metalink or by the hardware vendor. SAS and iSCSI connectivity is supported on Linux and Windows platforms.

If a tape device is no longer being manufactured, the availability has been noted as "Discontinued". Oracle Secure Backup continues to support these legacy devices as originally qualified.

The Virtual Tape Libraries (VTL) listed on this matrix are supported when configured to emulate tape drive(s) and/or tape libraries that are supported by Oracle Secure Backup.

This device support matrix is applicable to Oracle Secure Backup and Oracle Secure Backup Express as licensing permits.

This compatibility matrix includes the tape device "Product ID" which is the identifier that the device reports in response to a SCSI inquiry command.

If the Patch Req. column on this matrix indicates "yes", then the ob_robots and ob_drives files must be updated before deploying the device within an OSB domain. Please refer to Metalink Note 420583.1 for instructions on obtaining and updating the files. If the Patch Req. column lists an OSB version number, upgrade to that patch version or update the device

| Tape Drives | | | | | | | | |
|-------------|------------------|-----------------------------|------------|----------------------|------------------------|------------|----------|--|
| Tape Format | Vendor | Drive Description / Model # | Product ID | Native Capacity (GB) | Latest Firmware Tested | Patch Req. | Comments | Device Availability from Vendor |
| 8mm | Exabyte | EXB-8900 | EXB-8900 | 20 | | | | Discontinued |
| 8mm | Exabyte | Mammoth-2 | Mammoth2 | 60 | | | | |
| 3592 | IBM | 3592 | 03592J1A | Varies | 172E | | | |
| 9840 | Sun / StorageTek | 9840 | 9840 | 20 | | | | Discontinued |
| 9840 | Sun / StorageTek | T9840B | T9840B | 20 | | | | Discontinued |
| 9840-C | Sun / StorageTek | T9840C | T9840C | 40 | | | | |
| 9840-D | Sun / StorageTek | T9840D | T9840D | 75 | 1.35 | | | |
| 9940-1 | Sun / StorageTek | T9940A | T9940A | 60 | | | | Discontinued |
| 9940-1 | Sun / StorageTek | T9940B | T9940B | 200 | | | | |
| AIT-1 | Sony | SDX-400C | SDX-400C | 25 | | | | |
| AIT-1 | Sony | SDX-410C | SDX-410C | 25 | | | | |
| AIT-2 | Sony | SDX-500C | SDX-500C | 50 | | | | |
| AIT-2 | Sony | SDX-510C | SDX-510C | 50 | | | | |
| AIT-3 | Sony | SDX-700C | SDX-700C | 130 | | | | |
| AIT-3 | Sony | SDX-700V | SDX-700V | 130 | 100 | | | |
| AIT-4 | Sony | SDX-900V | SDX-900V | 200 | 0101 | | | |
| AIT-5 | Sony | SDX-1100 | SDX-1100 | 400 | 0100 | | | |
| DAT72 | HP | StorageWorks DAT72 | C7438A | 36 | | | | |
| DAT72 | Quantum | Seagate DAT 72 | DAT72 | 36 | A1A0 | | | |
| DAT72 | Sun / StorageTek | StorEdge DAT 72 | C7438A | 36 | | | | |
| DAT160 | HP | StorageWorks DAT160 | DAT160 | 80 | | | | |
| DLT | Quantum | DLT-S4 | DLT-S4 | 800 | 1414 | | | |
| DLT | Quantum | DLT-V4 | DLT-V4 | 160 | 0800 | | | |
| DLT | Sun / StorageTek | StorEdge DLT8000 Flexipack | DLT8000 | 40 | | | | Discontinued |
| LTO | HP | Ultrium 215, 230, 232 | Ultrium | 100 | | | | Ultrium 215 and 230 have been Discontinued |
| LTO | IBM | TotalStorage 3580 | ULT3580 | 100 | | | | |

Oracle Secure Backup 10.3 provides key management and support for LTO-4 tape drive encryption.

WORM functionality / tapes are not supported.

| Tape Drives | | | | | | | | |
|-------------|------------------|-----------------------------------|------------------------|----------------------|------------------------|------------|----------|---------------------------------|
| Tape Format | Vendor | Drive Description / Model # | Product ID | Native Capacity (GB) | Latest Firmware Tested | Patch Req. | Comments | Device Availability from Vendor |
| LTO | IBM | TotalStorage T200 and T200/F | ULTRIUM-TD1 | 100 | | | | |
| LTO | Quantum | Seagate Viper 200 | ULTRIUM06242 | 100 | | | | |
| LTO | Dell | PV110T, LTO | ULTRIUM06242 | 100 | | | | |
| LTO-2 | Quantum | Ultrium 2 Half Height | | 200 | 1783 | | | |
| LTO-2 | Quantum | Ultrium 2 Full Height | | 200 | 1703 | | | |
| LTO-2 | HP | Ultrium 460 | Ultrium 2 | 200 | | | | Discontinued |
| LTO-2 | HP | StorageWorks 448 | Ultrium 2 | 200 | | | | |
| LTO-2 | IBM | TotalStorage T400 and T400/F | ULTRIUM-TD2 | 200 | 4770 | | | |
| LTO-2 | Sun / StorageTek | StorEdge LTO 2 | Ultrium 2 | 200 | | | | |
| LTO-3 | Quantum | Ultrium 3 Full Height | ULTRIUM-TD3 | 400 | 1770 | | | Discontinued |
| LTO-3 | HP | Ultrium 960 | Ultrium 3 | 400 | G27D | | | |
| LTO-3 | IBM | TotalStorage T800 and T800/F | ULTRIUM-TD3 | 400 | 59D2 | | | |
| LTO-3 | Dell | PV110T, LTO3 | ULTRIUM-TD3 | 400 | 59D2 | | | |
| LTO-3 | Sun / StorageTek | Ultrium 960 | Ultrium 3 | 400 | G27D | | | |
| LTO-4 | HP | Ultrium-4 | Ultrium | 800 | H22S | | | |
| LTO-4 | HP | StorageWorks LTO1760, Half height | Ultrium | 800 | W22D | | | |
| LTO-4 | IBM | Ultrium-4 | ULTRIUM-TD4 | 800 | 7381 | | | |
| LTO-4 | Dell | Dell Powervault LTO4-120 FH | ULTRIUM-TD4 | 800 | 7381 | | | |
| LTO-4 | Sun / StorageTek | Ultrium-4 | Ultrium or ULTRIUM-TD4 | 800 | | | | |
| RXT | Spectra Logic | RXT Sabre | ULTRIUM-TD2 | | 4850 | | | |
| SAIT | Sony | SDZ-100 | SDZ-100 | 500 | 200 | | | |

Oracle Secure Backup 10.3 provides key management and support for LTO-4 tape drive encryption.

WORM functionality / tapes are not supported.

| Tape Drives | | | | | | | | |
|-------------|------------------|-----------------------------|------------|----------------------|------------------------|------------|----------|---------------------------------|
| Tape Format | Vendor | Drive Description / Model # | Product ID | Native Capacity (GB) | Latest Firmware Tested | Patch Req. | Comments | Device Availability from Vendor |
| SDLT220 | Quantum | Super DLT 220 | SuperDLT1 | 110 | | | | Discontinued |
| SDLT220 | Sun / StorageTek | StorEdge SDLT 220 | SuperDLT1 | 110 | | | | Discontinued |
| SDLT320 | Quantum | Super DLT 320 | SDLT320 | 160 | | | | |
| SDLT320 | Sun / StorageTek | StorEdge SDLT 320 | SDLT320 | 160 | | | | |
| SDLT600 | Quantum | Super DLT600 | SDLT600 | 300 | 1E1E | | | |
| SDLT600 | Sun / StorageTek | Super DLT600 | SDLT600 | 300 | 1E1E | | | |
| T10000 | Sun / StorageTek | T10000A | T10000 | 500 | 1.32 | | | |
| T10000B | Sun / StorageTek | T10000B | T10000B | 1000 | 1.37 | Yes | | |
| VS80 | Quantum | VS80 | VS80 | 40 | | | | |
| VS160 | Quantum | VS160 | DLT VS160 | 80 | | | | |
| VXA-1 | Exabyte | VXA-1 | VXA-1 | 33 | | | | |
| VXA-2 | Exabyte | VXA-2 | VXA-2 | 80 | | | | |

Oracle Secure Backup 10.3 provides key management and support for LTO-4 tape drive encryption.

WORM functionality / tapes are not supported.

Virtual Tape Libraries

| Vendor | Vendor / Model | Latest Firmware Tested | Patch Req. | Product ID | NDMP Direct Copy (Server-less Duplication) | Comments | Device Availability from Vendor |
|-------------------|--|----------------------------------|------------|--------------|--|--|---------------------------------|
| ADIC | Pathlight VX | 240A | | Pathlight VX | | Requires vendor firmware version: 2.4.1. The default Pathlight VX mode is available with Oracle Secure Backup 10.1.0.2. Using a supported emulated device is supported by Oracle Secure Backup 10.1 forward. | |
| Copan | Copan 200T | | | | | | |
| EMC | EMC DL210, DL310, DL710, DL720, DL740, DL4100, DL4200, DL4400, DL4106, DL4206 & DL4406 | 3.1 | | svtIRobot | | | |
| EMC | EMC Disk Library 1500, 3000 | 1.0.0 build 6.1.329 | | Disk Library | Supported | NDMP Direct Copy referred to as "Path to Tape", (PTT) option | |
| Data Domain | DD 460 | 4.0.3.0-31088 | | | | | |
| FalconStor | FalconStor VTL | 5.0 | | | Supported | | |
| HP | StorageWorks D2D110 Backup System | | | | | iSCSI connectivity supported on Linux only, USB connectivity not supported | |
| HP | VLS6500 | | | | | | Discontinued |
| HP | VLS9000, VLS12000 | | | | | | |
| Network Appliance | Netapp | OS versions: 5.5, 5.6.2 [#15983] | | | | Configure the custom library option with a tape device currently supported by Oracle Secure Backup. Network Appliance library type is not supported. | |
| Overland Storage | Overland Storage REO Series | 0425 | | | | iSCSI connectivity supported on Linux | |
| Quantum | DXi3500 | 04.00.141 | | | | | |
| Quantum | DXi5500 | 04.00.141 | | | | | Discontinued |
| Quantum | DXi7500 | 1.0.0 | | | Supported | NDMP Direct Copy referred to as "Application Specific Path to Tape" option | |
| Sepaton | Sepaton S2100-ES2 | | | | | | |
| Spectra | Spectra nTier300, nTier500, nTier700 | | | | | | |
| Sun | Sun VTL Plus, Prime | 3.15 | Yes | VTL | | | |

NDMP Direct Copy enables server-less tape duplication and is supported with virtual tape libraries as indicated above. The physical tape drives used for server-less duplication from virtual to physical tape may be shared drives (as in Storage Area Networks - SAN) or dedicated to the VTL.

Physical Tape Libraries

ADIC

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|---|-------|------------------------|------------|------------|----------|---------------------------------|
| Please refer to the Quantum section for listing of supported ADIC tape libraries. | | | | | | |

Breece Hill

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|-------------|-------------------|------------------------|------------|------------|----------|---------------------------------|
| Breece Hill | 8-Pak | 1.38 | | 108 | | |
| Breece Hill | 10-Pak | 1.47 | | 110 | | |
| Breece Hill | 15-Pak (Q2.15) | | | Q2 | | Discontinued |
| Breece Hill | 50-Pak (Q4.50) | | | 4.50 | | |
| Breece Hill | Q140 | | | Q140 | | |
| Breece Hill | Q210 | | | Q210 | | Discontinued |
| Breece Hill | Q4.30 DLT Library | | | Q4 | | Discontinued |
| Breece Hill | Q47 | | | Quad 47 | | Discontinued |
| Breece Hill | Q7 | | | Quad 7 | | Discontinued |
| Breece Hill | Q70 | | | Q70 | | Discontinued |
| Breece Hill | QSx70 (Saguaro) | | | QSx70 | | Discontinued |

Dell

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|--------|-------------------|------------------------|------------|--------------|----------|---------------------------------|
| DELL | PowerVault 122T | | | PV-122T | | Discontinued |
| DELL | PowerVault 124T | | | PV-124T | | |
| DELL | PowerVault 128T | | | C7200 | | Discontinued |
| DELL | PowerVault 130T | | | PV-130T | | Discontinued |
| DELL | PowerVault 132T | 227D | | PV-132T | | |
| DELL | PowerVault 136T | 3.21 | | PV-136T | | Discontinued |
| DELL | PowerVault 160T | 200A | | Scalar i2000 | | Discontinued |
| DELL | PowerVault ML6000 | 200G | | Scalar i500 | | |
| DELL | PowerVault TL2000 | | | 3573-TL | | |
| DELL | PowerVault TL4000 | | | 3573-TL | | |

Exabyte

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|---------|--------------|------------------------|------------|------------------|----------|---------------------------------|
| Exabyte | 110L | | | Exabyte 110L | | |
| Exabyte | 17D | | | Exabyte 17D | | Discontinued |
| Exabyte | 18D | | | Exabyte 18D | | Discontinued |
| Exabyte | 215 | | | Exabyte 215 | | |
| Exabyte | 221L | | | Exabyte 221L | | |
| Exabyte | 230D | | | Exabyte 230D | | Discontinued |
| Exabyte | 430 | | | Exabyte 430 | | |
| Exabyte | EZ17 | | | Exabyte EZ17 | | |
| Exabyte | Magnum20 | | | Magnum20 | | |
| Exabyte | X200 | | | Exabyte X200 | | Discontinued |
| Exabyte | X80 | | | Exabyte X80 | | Discontinued |
| Exabyte | AutoPak 1x10 | | | VXA AutoPak 1x10 | | |

HP

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|--------|----------------------------------|------------------------|------------|---------------|----------|---------------------------------|
| HP | StorageWorks 1/8 Tape Autoloader | | | ThinStor | | |
| HP | StorageWorks MSL2024 | | | MSL G3 Series | | |
| HP | StorageWorks MSL4048 | | | MSL G3 Series | | |
| HP | StorageWorks MSL5026DLX | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5026S2 | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5026SL | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5030L1 | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5052S2 | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5052SL | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL5060L1 | | | MSL5000 | | Discontinued |
| HP | StorageWorks MSL6000 | | | MSL6000 | | |
| HP | StorageWorks MSL6030 | | | MSL6030 | | |
| HP | StorageWorks MSL6060 | | | MSL6060 | | |
| HP | StorageWorks ESL286E | | | ESL E-Series | | |
| HP | StorageWorks ESL322E | | | ESL E-Series | | |
| HP | StorageWorks ESL630E | | | ESL E-Series | | |
| HP | StorageWorks ESL712E | | | ESL E-Series | | |
| HP | SureStore DAT24x6 (C1559) | | | C1559 | | Discontinued |
| HP | SureStore DAT24x6 (C1557) | | | C1557 | | Discontinued |
| HP | SureStore DAT40x6 (C5713) | | | C5713A | | Discontinued |

IBM

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|--------|------------------------------------|------------------------|------------|------------|----------|---------------------------------|
| IBM | 3581 Ultrium Autoloader | | | ULT3581 | | |
| IBM | 3582 Tape Library | | | ULT3582 | | |
| IBM | 3583 Tape Library | | | ULT3583 | | |
| IBM | 3584 Tape Library | | | 03584 | | |
| IBM | TS3100/3200 System Storage Library | 1.1 | | 3573-TL | | |
| IBM | TS3310 System Storage Library | | | 3576-MTL | | |

Overland Storage

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|----------|------------|------------------------|------------|------------|--|---------------------------------|
| Overland | LibraryPro | | | LIBRARYPRO | | Discontinued |
| Overland | LXB Series | | | LXB | | Discontinued |
| Overland | Neo 2000 | 429 | | NEO Series | Gbe NDMP option supported with minimum firmware version of 3.22, GbE iSCSI option supported on Linux | |
| Overland | Neo 4100 | | | NEO Series | | |
| Overland | Neo 4200 | | | NEO Series | | |
| Overland | Neo 4300 | | | NEO Series | | |
| Overland | Neo 4400 | | | NEO Series | | |
| Overland | Neo 8000 | | | NEO Series | | |

NEC

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|--------|---------------------|------------------------|------------|------------|----------|---------------------------------|
| NEC | NEC T16A Autoloader | 0001 | | T16A | | |
| NEC | NEC T40A Library | 0004 | | T40A | | |
| NEC | NEC T40A-2 Library | 0004 | | T40A2 | | |

Qualstar

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|----------|-----------------|------------------------|------------|------------|----------|---------------------------------|
| Qualstar | RLS-4000 Series | | | RLS | | |
| Qualstar | RLS-5000 Series | | | RLS | | |
| Qualstar | RLS-6000 Series | | | RLS | | |
| Qualstar | RLS-8000 Series | | | RLS | | |
| Qualstar | TLS-4000 Series | | | TLS-4 | | |
| Qualstar | TLS-5000 Series | 2.22 | | TLS-5 | | |
| Qualstar | TLS-6000 Series | | | TLS-6 | | |
| Qualstar | TLS-8000 Series | | | TLS-8 | | |

Quantum

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|---------|-----------------------|------------------------|------------|--------------|---------------------------------|---------------------------------|
| ADIC | FastStor 2 | | | FastStor | | Discontinued |
| ADIC | Scalar 10K | 210A | | Scalar 10k | Mixed media mode not supported. | |
| ADIC | Scalar 24 | 107A | | Scalar 24 | | |
| ADIC | Scalar 50 | | | Scalar 50 | | |
| ADIC | Scalar 100 | | | Scalar 100 | | Discontinued |
| ADIC | Scalar 1000 | | | Scalar 1000 | | Discontinued |
| ADIC | Scalar i500 | 200G | | Scalar i500 | | |
| ADIC | Scalar i2000 | 120A | | Scalar i2000 | | |
| ATL | ATL 7100 | | | ATL7100 | | Discontinued |
| ATL | ATL Powerstor L200 | | | L200 | | Discontinued |
| ATL | ATL Powerstor L500 | | | L500 | | Discontinued |
| ATL | DLT-2500 Autoloader | | | DLT2500 | | Discontinued |
| ATL | DLT-2500XT Autoloader | | | DLT2500 | | Discontinued |
| ATL | DLT-2700 Autoloader | | | DLT2700 | | Discontinued |
| ATL | DLT-4500 Autoloader | | | DLT4500 | | Discontinued |
| ATL | DLT-4700 Autoloader | | | DLT4700 | | Discontinued |
| ATL | DLTstor114 Autoloader | | | DLT Changer | | Discontinued |
| Quantum | M1500 | | | 1500 | | Discontinued |
| Quantum | M1800 | | | 1500 | | Discontinued |
| Quantum | M2500 | | | M2500 | | Discontinued |
| Quantum | P4000 | | | P4000 | | Discontinued |
| Quantum | P7000 | | | P7000 | | Discontinued |
| Quantum | PX 500 | | | PX500 | | Discontinued |
| Quantum | PX 720 | 3 | | PX720 | | |
| Quantum | SuperLoader | 002D | | UHDL | | Discontinued |
| Quantum | SuperLoader 3 | 002D | | UHDL | | |

Sony

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|--------|--------------|------------------------|------------|------------|----------|---------------------------------|
| Sony | Lib 81 / A3 | 106 | | LIB-81 | | |
| Sony | Lib - 162 | | | LIB-162 | | |
| Sony | Lib - D81 | 104 | | LIB-D81 | | |
| Sony | Library 152 | | | 215 | | |
| Sony | Library 152E | | | 215 | | |
| Sony | Library 302 | | | 215 | | |
| Sony | TSL-A500C | | | TSL-A500C | | |

Spectra Logic

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|---------------|-------|------------------------|------------|------------|--|---------------------------------|
| Spectra Logic | 10k | | | 10000 | | |
| Spectra Logic | 2k | | | 215 | | |
| Spectra Logic | 12k | | | GATOR | | Discontinued |
| Spectra Logic | 20k | | | GATOR | | |
| Spectra Logic | 64k | | | GATOR | | |
| Spectra Logic | T50 | 2000 | | PYTHON | | |
| Spectra Logic | T120 | 2000 | | PYTHON | BlueScale 9.0 or greater must be used with SAIT drives | |
| Spectra Logic | T950 | 2000 | | PYTHON | | |

Sun / StorageTek

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|------------------|---------------------------------|------------------------|------------|---------------|--|---------------------------------|
| Sun / StorageTek | 9704 Tape Library (LAGO LS/340) | | | LS-340 | | |
| Sun / StorageTek | L180 Library | | | L180 | | |
| Sun / StorageTek | L20 Tape Library | | | L20 | | |
| Sun / StorageTek | L40 Tape Library | | | L40 | | |
| Sun / StorageTek | L700 Library | | | L700 | L700e(Single frame) support only. L700e (Dual Frame) is not supported. | |
| Sun / StorageTek | StorEdge C2 | 002D | | UHDL | | |
| Sun / StorageTek | StorEdge C4 | | | PX500 | | |
| Sun / StorageTek | StorEdge L7 | | | FastStor | | Discontinued |
| Sun / StorageTek | StorEdge L8 | | | FastStor | | Discontinued |
| Sun / StorageTek | StorEdge L25 | | | M1500 | | Discontinued |
| Sun / StorageTek | StorEdge L1000 | | | P1000 | | Discontinued |
| Sun / StorageTek | StorEdge L20 | | | C7200 | | Discontinued |
| Sun / StorageTek | StorEdge L40 | | | C7200 | | Discontinued |
| Sun / StorageTek | StorEdge L60 | | | C7200 | | Discontinued |
| Sun / StorageTek | StorEdge L100 | | | M2500 | | Discontinued |
| Sun / StorageTek | StorEdge L180 | | | L180 | | Discontinued |
| Sun / StorageTek | StorEdge L700 | | | L700 | | |
| Sun / StorageTek | SL24 Tape Autoloader | | | MSL G3 Series | | |
| Sun / StorageTek | SL48 Tape Library | | | MSL G3 Series | | |
| Sun / StorageTek | SL500 | | | SL500 | | |
| Sun / StorageTek | SL3000 | 2.02 | | SL3000 | Advanced Exchange Module (AEM) is not supported. | |

ACSLs Supported Devices

| Vendor | Model | Latest Firmware Tested | Patch Req. | Product ID | Comments | Device Availability from Vendor |
|---|---------------------|------------------------|------------|------------|--------------------|---------------------------------|
| Sun / StorageTek | Powder Horn 9310 | | | ACSLs | | Discontinued |
| Sun / StorageTek | Timber Wolf 9740 | | | ACSLs | SCSI-Attached only | Discontinued |
| Sun / StorageTek | L20, L40, L80, L180 | | | ACSLs | | Discontinued |
| Sun / StorageTek | L700e | | | ACSLs | | |
| Sun / StorageTek | SL500 | | | ACSLs | | |
| Sun / StorageTek | SL1400 | | | ACSLs | | |
| Sun / StorageTek | L5500 | | | ACSLs | | Discontinued |
| Sun / StorageTek | SL8500 | | | ACSLs | | |
| NOTE: All ACSLS supported devices require use of ACSLS version 7.x or higher. | | | | | | |